

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b><u>FL-RU2003</u></b>	07/05/18	(M)FL	Russia	FL_BDP
Commentary 1. Counterfeit protection has been improved based on scans of 1000 RUB counterfeits received from customer. 2. Acceptance rate for 2000 RUB (2017) has been improved.				
<b><u>FL-RU2002</u></b>	05/17/18	(M)FL	Russia	FL_BDP
Counterfeit protection has been improved based on scans of 1000 RUB counterfeits received from customer.				
<b><u>FL-RU2001</u></b>	03/01/18	(M)FL	Russia	FL_BDP
1. Processing of two new bill types 200 RUB (2017) and 2000 RUB (2017) has been introduced based on scans received from customer. 2. "Bill Table #1" option has been removed as per customer request. "Bill Table #0" is used as default ("Bill Table"). 3. Bill Table has been modified to include new bill types (refer to User's Guide for details): Escrow Code "61H" has been set to "200 RUB"; Escrow Code "62H" has been set to "2000 RUB". 4. DIP Switches settings have been changed to include new bill types (refer to User's Guide for details): DIP Switch 1.4 is set to "200 RUB", DIP Switch 1.7 is set to "2000 RUB".				
<b><u>FL-RU2152</u></b>	03/15/17	(M)FL	Russia	FL_BDP
Counterfeit protection has been improved based on scans of 500 RUB counterfeits received from customer.				
<b><u>FL-RU2151</u></b>	06/03/16	(M)FL	Russia	FL_BDP
1. Counterfeit protection has been improved based on scans of 500, 1000 and 5000 RUB counterfeits received from customer. 2. Greeting message was changed from "Cash Code" to "SUZOHAPP".				
<b><u>FL-RU2149</u></b>	11/11/14	(M)FL	Russia	FL_BDP
Bill Tables have been corrected.				
<b><u>FL-RU2148</u></b>	08/05/14	(M)FL	Russia	FL_BDP
1. Overall acceptance rate has been improved. 2. Processing of old 10 RUB (1997) has been disabled.				
<b><u>FL-RU2147</u></b>	11/18/13	(M)FL	Russia	FL_BDP
Performance improvement to 500 and 5000 RUB.				

<b><u>FL-RU2146</u></b>	07/31/13	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Performance improvement to 10, 50, 100, 500, 1000 and 5000 RUB.</li> <li>2. Overall acceptance rate has been improved based on the latest samples of street grade bills.</li> </ol>				
<b><u>FL-RU2145</u></b>	02/28/12	(M)FL	Russia	FL_BDP
Processing of new 500 and 5000 RUB issued in 2011 has been introduced.				
<b><u>FL-RU2644</u></b>	02/01/11	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Processing of new 1000 RUB issued in 2010 has been introduced.</li> <li>2. Overall acceptance has been improved according to the latest samples of street money.</li> </ol>				
<b><u>FL-RU2642</u></b>	03/25/10	(M)FL	Russia	FL_BDP
Counterfeit protection has been improved based on the latest samples of 5000 RUB counterfeit.				
<b><u>FL-RU2641</u></b>	01/15/10	(M)FL	Russia	FL_BDP
Counterfeit protection has been improved based on the latest samples of 5000 RUB counterfeit.				
<b><u>FL-RU2640</u></b>	06/02/09	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Counterfeit protection has been improved according to the latest samples of 1000 RUB counterfeits.</li> <li>2. Acceptance of 50 and 100 RUB has been improved based on the latest samples of bills printed out in 2008-2009.</li> </ol>				
<b><u>FL-RU2639</u></b>	09/16/08	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Counterfeit protection has been improved according to the latest samples of glued 1000 &amp; 5000 RUB bills.</li> <li>2. Overall acceptance has been improved based on the latest samples of street grade bills.</li> <li>3. Stacker cycle has been added in case of rejecting from stacking state.</li> <li>4. "Program signature" command has been introduced.</li> <li>5. Rejecting code "Feed error"(0x75) changed to "Insertion error"(0x71).</li> <li>6. Cassette presence checking added when bill is held in the entry slot.</li> <li>7. Pause state will occur only if both Input and Aligning sensors covered.</li> <li>8. 10 sec timeout implemented in Pause state.</li> </ol>				
<b><u>FL-RU2638</u></b>	08/20/07	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Counterfeit protection has been enhanced according to the latest samples of 10 RUB counterfeits.</li> <li>2. Occasional sticking of the bills in aligning mechanism has been eliminated by increase the setting time for oval wheel.</li> </ol>				
<b><u>FL-RU2636</u></b>	06/06/07	(M)FL	Russia	FL_BDP
Protection against glued counterfeits has been improved according to the latest samples of counterfeit money.				
<b><u>FL-RU2635</u></b>	11/15/06	(M)FL	Russia	FL_BDP
Acceptance rate of 5000 RUB has been improved based on the latest samples of street grade bills.				

July 5, 2018

<b><u>FL-RU2634</u></b>	09/29/06	(M)FL	Russia	FL_BDP
Processing of new 5000 RUB issued in 2006 has been introduced.				
<b><u>FL-RU2533</u></b>	03/29/06	(M)FL	Russia	FL_BDP
Counterfeit protection has been enhanced according to the latest over-painted fakes.				
<b><u>FL-RU2531</u></b>	02/14/06	(M)FL	Russia	FL_BDP
<ol style="list-style-type: none"> <li>1. Overall acceptance rate has been improved according to the latest samples of street money.</li> <li>2. Credit recovery option for Barcode coupon has been implemented.</li> <li>3. Part number and Boot version information has been included in statistics.</li> <li>4. Statistics counter "Jam at Entrance" has been changed to "Returned bills by Cross Sensor".</li> <li>5. Excel export support in statistics has been implemented.</li> </ol>				
<b><u>FL-RU2529</u></b>	07/28/05	(M)FL	Russia	FL_BDP
Acceptance of 1000 RUB (old and new) has been improved based on the latest samples of street money.				
<b><u>FL-RU2528</u></b>	05/20/05	(M)FL	Russia	FL_BDP
Counterfeit Protection against glued bills from customer				
<b><u>FL-RU2527</u></b>	04/26/05	(M)FL	Russia	FL_BDP
Protection against glued bills				
<b><u>FL-RU2526</u></b>	03/23/05	(M)FL	Russia	FL_BDP
Unauthorized FL reset due to communication problem between main program and sensor set software has been eliminated				
<b><u>FL-RU2525</u></b>	03/10/05	(M)FL	Russia	FL_BDP
Bug in processing of bill insertion has been fixed.				
<b><u>FL-RU2524</u></b>	01/17/05	(M)FL	Russia	FL_BDP
Anti-string improvement: identification of bill in channel during stacking; "Stack1" and "Stack2" events were combined into one event.				
<b><u>FL-RU2523</u></b>	11/10/04	(M)FL	Russia	FL_BDP
Processing of 10; 50; 100; 500; 1000 Rubles issued in 2004 has been added.				
<b><u>FL-RU2522</u></b>	07/19/04	(M)FL	Russia	FL_BDP
ID code (Boot version) has been changed to B319.				