

April 26, 2018

Revision History

Item No.		Release Date	Device	Country	Comm. Protocol				
Co	Commentary								
FL-ZA7824	:	04/26/18	(M)FL	South Africa	CCS-VFM				
1. 2. 3. 4. Lim 1.	 anniversary of the birth of Nelson Mandela, has been introduced. 2. Support of banknotes with OMRON feature has been added. 3. Processing of old 10, 20, 50, 100 and 200 ZAR, issued before 2005, has been disabled. 4. Statistics counters have been modified. Limitations: 								
FL-ZA7823		05/24/16	(M)FL	South Africa	CCS-VFM				
	has been improved.								
FL-ZA7822		05/01/15	(M)FL	South Africa	CCS-VFM				
1. 2.	field).								
FL-ZA7821		06/20/13	(M)FL	South Africa	CCS-VFM				
Overall acceptance rate has been improved based on the latest samples of street grade bills.									
FL-ZA7820		08/31/12	(M)FL	South Africa	CCS-VFM				
1. 2.	Processing of new 10, 20, 50, 100 and 200 ZAR to be issued in 2012 has been introduced. DIP switch to enable / disable old ZAR acceptance has been brought in.								
FL-ZA7819		07/18/11	(M)FL	South Africa	CCS-VFM				
1. 2.	Processing of stained notes has been improved based on the latest samples of stained bills. Overall acceptance rate has been improved according to the latest samples of street grade bills.								
FL-ZA7818		04/28/10	(M)FL	South Africa	CCS-VFM				
FL-ZA7817	cessing of old 200 ZAF	03/13/09	(M)FL	South Africa	CCS-VFM				



April 26, 2018

DIP switch "High Acceptance / High Security" sets acceptance mode for stained notes.

<u>FL-ZA7816</u> 09/18/08 (M)FL South Africa CCS-VFM

- 1. Bill processing has been improved to reject stained ZAR notes.
- 2. Overall acceptance rate has been improved according to the latest samples of street grade bills.
- 3. Stacker cycle added in case of rejecting from Stacking state.

First release.

4. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.

<u>FL-ZA7815</u>	11/09/06	(M)FL	South Africa	CCS-VFM				
Overall acceptance rate has been improved according to the latest samples of street grade bills.								
FL-ZA7814	08/15/06	(M)FL	South Africa	CCS-VFM				
Message "Drop Box FULL" (0x8D) is used for failures and jam conditions instead of FAILURE (0x8C).								
FL-ZA7813	08/14/06	(M)FL	South Africa	CCS-VFM				
Message "Drop Box removed" (0x8E) is used instead of FAILURE (0x8C).								
FL-ZA7812	07/26/06	(M)FL	South Africa	CCS-VFM				

SUZOHAPP • 1743 Linneman Road • Mount Prospect, IL 60056 • Phone: 847-593-6130 • Fax: 847-593-6137