June 26, 2018

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol			
Commentary							
FL-ZANA7820	06/26/18	(M)FL	South Africa + Namibia	CCS-VFM			
the birth of 2. Processing of	of new 10, 20, 50, 100 and 2 Nelson Mandela, has been of old 10, 20, 50 and 100 ZA eptance rate has been impro	introduced. R, issued before 200	018 to commemorate the 100th a 05, has been disabled.	nniversary of			
FL-ZANA7819	12/04/17	(M)FL	South Africa + Namibia	CCS-VFM			
customer. 2. Support of 2 2014). 3. Overall acce		feature has been ad	en improved based on scans recei dded (series 2012, banknotes prin				
FL-ZANA7818	12/22/15	(M)FL	South Africa + Namibia	CCS-VFM			
2. Overall acce	of new 10 NAD (2015) and 2 eptance rate has been impro essage was changed from "(oved.					
FL-ZANA7817 Overall accepta	05/22/14 nce rate has been improved	(M)FL	South Africa + Namibia	CCS-VFN			
FL-ZANA7816	02/28/13	(M)FL	South Africa + Namibia	CCS-VFM			
1. Processing of	of new 10, 20, 50, 100 and 2 o enable / disable old ZAR a	200 ZAR issued in 20					
FL-ZANA7815	07/10/12	(M)FL	South Africa + Namibia	CCS-VFIV			
Processing of n	ew 10 NAD, 20 NAD, 50 NA	D, 100 NAD and 200) NAD issued in 2012 has been int	roduced.			
FL-ZANA7814	08/17/10	(M)FL	South Africa + Namibia	CCS-VFM			
Processing of c	ld 200 ZAR has been disable	ed.					
FL-ZANA7813	03/26/10	(M)FL	South Africa + Namibia	CCS-VFM			
Acceptance of	10 NAD has been improved	based on the latest	samples of street grade bills.				
FL-ZANA7812	10/07/09	(M)FL	South Africa + Namibia	CCS-VFM			
1. Overall acce	eptance rate has been impro	oved based on the la	atest samples of street grade bills.				

June 26, 2018

2. DIP switch "High Acceptance / High Security" sets acceptance mode for stain notes.

<u>FL-ZANA7811</u>		06/03/08	(M)FL	South Africa + Namibia	CCS-VFM			
1.	Country selection by DIP switch has been excluded. This SW accepts both ZAR and NAD with the same credit for the same denomination.							
2.	. Pause state will occur only if both Input and Aligning sensors covered.							
3.	10 sec timeout implemented in Pause state.							
4.	Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.							
<u>FL-ZANA7810</u>		09/21/07	(M)FL	South Africa + Namibia	CCS-VFM			
Fir	st release.							