

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>FL-ZM2016</b>	05/01/19	(M)FL	Zambia	FL_BDP
<p><b>Commentary</b></p> <ol style="list-style-type: none"> <li>1. Processing of new 2, 5, 10, 20, 50 and 100 ZMW series 2018 has been introduced.</li> <li>2. Overall acceptance rate has been improved.</li> </ol>				
<b>FL-ZM2015</b>	11/16/17	(M)FL	Zambia	FL_BDP
<ol style="list-style-type: none"> <li>1. Processing of 2, 5, 10, 20, 50 and 100 ZMW series 2015 has been added.</li> <li>2. Overall acceptance rate has been improved based on scans received from customer.</li> <li>3. Greeting message has been changed to "SUZOHAPP".</li> </ol>				
<b>FL-ZM2014</b>	08/31/13	(M)FL	Zambia	FL_BDP
<ol style="list-style-type: none"> <li>1. Processing of new 2 and 5 ZMW issued in 2013 has been introduced.</li> <li>2. Acceptance of 10, 20, 50 and 100 ZMW has been improved based on the latest samples of street grade bills.</li> </ol>				
<b>FL-ZM2013</b>	05/22/13	(M)FL	Zambia	FL_BDP
<ol style="list-style-type: none"> <li>1. Processing of new 10, 20, 50 and 100 ZMW issued in 2013 has been introduced.</li> <li>2. Processing of old 10000, 20000 and 50000 ZMK has been disabled.</li> </ol>				
<b>FL-ZM2012</b>	07/23/08	(M)FL	Zambia	FL_BDP
<ol style="list-style-type: none"> <li>1. Processing of 10000 &amp; 20000 ZMK has been introduced.</li> <li>2. Stacker cycle added in case of rejecting from stacking state.</li> <li>3. Second byte of the Request Bill Enables command is not masked with 0xFF.</li> <li>4. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.</li> <li>5. Pause state will occur if both Input and Aligning sensors covered.</li> <li>6. 10 sec timeout implemented in Pause state.</li> <li>7. Country code has been changed to match JCM code (0x7F).</li> </ol>				
<b>FL-ZM2010</b>	12/11/07	(M)FL	Zambia	FL_BDP
<p>First release.</p>				