

Revision History

January 3, 2011

Page 1

No	Item No.	File Name	Release		Country	Comm. Protocol
			Date	Device		
		Commentary				
1	<u>FL-AM2612</u>	FL-AM6AAD0-4.12.hex	12/23/10	FL	Armenia	FL_BDP
		Processing of new 100000 AMD issued in 2009 has been introduced.				
2	<u>FL-AM2511</u>	FL-AM5AAD0-4.11.hex	11/04/08	FL	Armenia	FL_BDP
		1. Processing of 50000 AMD and new 20000 AMD issued in 2007 has been introduced.				
		2. Country code has been changed to match with JCM code (0x7C).				
		3. Rejecting code "Feed error"(0x75) has been replaced with "Insertion error"(0x71).				
		4. Program Signature command implemented.				
		5. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.				
		6. Pause state will occur only if both Input and Aligning sensors covered.				
		7. 10 sec timeout implemented in Pause state.				
3	<u>FL-AM2410</u>	FL-AM4AAD0-4.10.hex	08/17/07	FL	Armenia	FL_BDP
		First release.				