

Revision History

30. September 2009

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
Commentary						
1	<u>FL-CN1718</u>	FL-CN7AAJ1-5.18.hex	30/09/09	FL	China	CCNET
Counterfeit protection has been improved based on the latest samples of glued 100 CNY counterfeits.						
2	<u>FL-CN1717</u>	FL-CN7AAJ1-5.17.hex	03/11/08	FL	China	CCNET
1. Counterfeit protection has been improved according to the latest samples of glued 10, 20 & 100 CNY bills. 2. Acceptance of 10, 20, 50 & 100 CNY has been improved based on the latest samples of recently issued bills (printed out on new paper). 3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions. 4. Pause state will occur only if both Input and Aligning sensors covered. 5. 10 sec timeout implemented in Pause state. 6. Additional check for drop box presence has been implemented for case when returned bill is held at entry sensor.						
3	<u>FL-CN1716</u>	FL-CN7AAJ1-5.16.hex	02/04/08	FL	China	CCNET
1. Counterfeit protection has been improved according to the latest samples of glued 10, 20, 50 & 100 CNY counterfeits. 2. Acceptance rate of 50 & 100 CNY has been improved based on the latest samples of street grade bills.						
4	<u>FL-CN1715</u>	FL-CN7AAJ1-5.15.hex	20/02/07	FL	China	CCNET
Counterfeit protection has been enhanced according to the latest samples of 50 and 100 CNY counterfeits.						
5	<u>FL-CN1714</u>	FL-CN7AAJ1-5.14.hex	31/05/06	FL	China	CCNET
1. Counterfeit protection for 50 CNY has been enhanced according to the latest sample of fake 50 CNY received from the customer. 2. Acceptance of new 5 and 10 CNY issued in 2005 has been improved based on validating head received from the customer. 3. Part number and boot version information have been added to statistics. 4. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".						
6	<u>FL-CN1713</u>	FL-CN7AAJ1-5.13	09/02/06	FL	China	CCNET
1. Acceptance of new 50 & 100 CNY issued in 2005 has been improved according to the latest sample of street money. 2. Counterfeit protection for 10, 50 & 100 CNY has been enhanced based on the latest samples of fake money.						
7	<u>FL-CN1712</u>	FL-CN7AAJ1-4.12	14/10/05	FL	China	CCNET
Processing of new 5, 10, 20, 50, 100 CNY issued in 2005 has been added.						
8	<u>FL-CN1711</u>	FL-CN7AAJ1-4.11	07/07/05	FL	China	CCNET
Counterfeit protection has been improved according to latest counterfeit samples Metal bezel support has been implemented.						
9	<u>FL-CN1710</u>	FL-CN7AAJ1-4.10	23/07/04	FL	China	CCNET
Double-bill acceptance has been eliminated; 1 & 2 CNY bills processing and metal bezel support have been included						
10	<u>FL-CN1508</u>	FL-CN5AAJ1-4.16	28/08/03	FL	China	CCNET

No	Item No.	File Name	Release			Comm. Protocol	Page	2
			Date	Device	Country			
			Commentary					
			Fixed the problem with POWER UP state when box's removed.New barcode processing					