8. September 2008

Page 1

Revision History

Item No.	File Name	Release Date Device	Country	Comm. Protocol	
	Commentary				
FL-CZ2011	FL-CZ5AAD0-4.11.hex	08/09/08 FL	Czech Republic	FL_BDP	
	1. Processing of new 1000 CZK issued in 2008 and new 2000 CZK issued in 2008				
	has been introduce	ed.			
	Pause state will occur only if both Input and Aligning sensors covered.				
	3. 10 sec timeout implemented in Pause state.				
	4. Direction switch disabled.				
5. Program CRC in the Version string will match Program Signature (Seed=0).					
FL-CZ2510	FL-CZ5AAD0-4.10	01/11/04 FL	Czech Republic	FL_BDP	
	FL-CZ2011	FL-CZ2011 FL-CZ5AAD0-4.11.hex 1. Processing of new has been introduce 2. Pause state will od 3. 10 sec timeout imp 4. Direction switch di 5. Program CRC in the	FL-CZ2011 FL-CZ5AAD0-4.11.hex 08/09/08 FL 1. Processing of new 1000 CZK issued has been introduced. 2. Pause state will occur only if both Inp. 3. 10 sec timeout implemented in Paus 4. Direction switch disabled. 5. Program CRC in the Version string volume of the paus o	FL-CZ2510 File Name Commentary FL-CZ2011 FL-CZ5AAD0-4.11.hex 08/09/08 FL Czech Republic 1. Processing of new 1000 CZK issued in 2008 and new 2000 CZK has been introduced. 2. Pause state will occur only if both Input and Aligning sensors co 3. 10 sec timeout implemented in Pause state. 4. Direction switch disabled. 5. Program CRC in the Version string will match Program Signature. FL-CZ2510 FL-CZ5AAD0-4.10 01/11/04 FL Czech Republic	FL-CZ2011 FL-CZ2011 FL-CZ2011 FL-CZ5AAD0-4.11.hex 08/09/08 FL Czech Republic FL_BDP 1. Processing of new 1000 CZK issued in 2008 and new 2000 CZK issued in 2008 has been introduced. 2. Pause state will occur only if both Input and Aligning sensors covered. 3. 10 sec timeout implemented in Pause state. 4. Direction switch disabled. 5. Program CRC in the Version string will match Program Signature (Seed=0). FL-CZ2510 FL-CZ5AAD0-4.10 01/11/04 FL Czech Republic FL_BDP