

Revision History

12. May 2010

Page 1

No	Item No.	File Name	Release			Comm. Protocol
			Date	Device	Country	
		Commentary				
1	<u>FL-GB1316</u>	FL-GB3AAJ1-4.16.hex	12/05/10	FL	Great Britain	CCNET
		1. Processing of old 20 GBP has been disabled.				
		2. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.				
		3. Pause state will occur if both Input and Aligning sensors covered.				
		4. 10 sec timeout implemented in Pause state.				
		5. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.				
2	<u>FL-GB1315</u>	FL-GB3AAJ1-4.15.hex	15/03/07	FL	Great Britain	CCNET
		Processing of new 20 english pounds (GBP) issued in 2007 has been introduced.				
3	<u>FL-GB1314</u>	FL-GB3AAJ1-4.14	08/09/05	FL	Great Britain	CCNET
		The overall acceptance rate has been enhanced according to the latest samples of street money.				
4	<u>FL-GB1304</u>	FL-GB3AAJ1-4.13	15/08/03	FL	Great Britain	CCNET
		Added new 5 Pounds. Improved Credit Recovery. Close bill pass in Escrow.				