Revision History

No	Item No.	File Name Commentary	Release Date Device	Country	Comm. Protocol
1	<u>FL-MY1620</u>	to fix the problem v	vith accepting of tra ction has been impr	Malaysia signals has been implemented nsparent plastic 5 MYR bills. oved according to the latest samp	CCNET
3	<u>FL-MY1619</u>	FL-MY6AAJ1-4.19.hex Acceptance of new latest samples of st		Malaysia 007 has been improved according	CCNET g to the
4	<u>FL-MY1618</u>	of street grade bil 2. Rejecting code "("Insertion error"(0 3. Pause state will o 4. 10 sec timeout in	ls. Conv. error"(0x64) h x60) for wrong inser occur only if both Inperented in Paus box presence has lead	out and Aligning sensors covered.	
5	FL-MY1617	in stacking state i 2. Stacker cycle ha	nstead of Input2 ser s been added in cas	Malaysia ged: Synchro sensor is checked insor. e of rejecting from stacking state 2007 has been introduced.	
6	<u>FL-MY1616</u>	FL-MY6AAJ1-4.16.hex Overall acceptance of street grade bills.		Malaysia oved according to the latest samp	CCNET
7	<u>FL-MY1615</u>	FL-MY6AAJ1-4.15 09/30/05 FL Malaysia CCNET 1. 2 MYR acceptance has been improved based on the latest samples of street money. 2. Overall acceptance has been improved according to the latest incoming of street grade bills.			
8	<u>FL-MY1614</u>	FL-MY6AAJ1-4.14 1. Acceptance of 10 2. Processing of 2 I 3. Metal bezel supp	MYR bills has been	added.	CCNET
9	<u>FL-MY1513</u>	· · · · · · · · · · · · · · · · · · ·	proved based on la	Malaysia has been added; 2) Acceptance test samples of street money; 3)	
10	FL-MY1512	FL-MY5AAJ1-4.12 Acceptance of 10 &	08/12/04 FL 50 MYR has been	Malaysia improved	CCNET
11	FL-MY1502	FL-MY5AAJ1-4.11 First release	05/03/04 FL	Malaysia	CCNET