

# Revision History

June 22, 2011

Page 1

No	Item No.	File Name	Release			Country	Comm. Protocol
			Date	Device			
1	<u><a href="#">FL-MY5124</a></u>	FL-MY3AAH1-4.24.hex	06/22/11	FL	Malaysia	FL-BDG1	
		Commentary					
		1. Counterfeit protection has been improved according to the latest samples of 50 MYR suspect notes.					
		2. Overall acceptance has been improved based on the latest samples of street grade bills.					
2	<u><a href="#">FL-MY5123</a></u>	FL-MY3AAH1-4.23.hex	02/02/10	FL	Malaysia	FL-BDG1	
		Counterfeit protection has been improved according to the latest samples of 50 MYR counterfeits.					
3	<u><a href="#">FL-MY5122</a></u>	FL-MY3AAH1-4.22.hex	03/16/09	FL	Malaysia	FL-BDG1	
		1. Acceptance of new 50 MYR issued in 2007 has been improved based on the latest samples of street grade bills.					
		2. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.					
4	<u><a href="#">FL-MY5121</a></u>	FL-MY3AAH1-4.21.hex	03/19/08	FL	Malaysia	FL-BDG1	
		1. Processing of new 50 MYR issued in 2007 has been introduced.					
		2. Processing of 1, 2 and 5 MYR has been disabled.					
5	<u><a href="#">FL-MY5120</a></u>	FL-MY6AAH0-4.20.hex	07/10/06	FL	Malaysia	FL-BDG1	
		Overall acceptance rate has been improved according to the latest samples of street grade bills.					
6	<u><a href="#">FL-MY5119</a></u>	FL-MY6AAH0-4.19	01/30/06	FL	Malaysia	FL-BDG1	
		First two characters of Program revision have been changed from "FL" to "MY" to be returned on host controller's request (oxCC) through G1 interface.					
7	<u><a href="#">FL-MY5118</a></u>	FL-MY6AAH0-4.18	07/28/05	FL	Malaysia	FL-BDG1	
		1. Acceptance of 10, 50, 100 MYR has been improved.					
		2. Processing of 2 MYR bills has been added.					
		3. Processing of new 5 MYR issued in 2004 has been added.					
8	<u><a href="#">FL-MY5108</a></u>	FL-MY5AAH0-4.17	08/12/04	FL	Malaysia	FL-BDG1	
		Acceptance of 10 & 50 MYR has been improved					
9	<u><a href="#">FL-MY5107</a></u>	FL-MY5AAH0-4.16	08/06/04	FL	Malaysia	FL-BDG1	
		Bug in the command 'Write Current Configuration to Memory' has been fixed					
10	<u><a href="#">FL-MY5104</a></u>	FL-MY5AAH0-4.13	04/21/04	FL	Malaysia	FL-BDG1	
		Support of two bill tables has been added for compatibility with old host controllers					
11	<u><a href="#">FL-MY5503</a></u>	FL-MY5AAH0-4.12	04/07/04	FL	Malaysia	FL-BDG1	
		G1 interface support has been enhanced					
12	<u><a href="#">FL-MY5502</a></u>	FL-MY5AAH0-4.11	03/25/04	FL	Malaysia	FL-BDG1	
		New methodology of double bills identification has been worked out					
13	<u><a href="#">FL-MY5501</a></u>	FL-MY5AAH0-4.10	02/23/04	FL	Malaysia	FL-BDG1	
		First release					