Page 1

Revision History

No	Item No.	File Name		Release Date Device	Country	Comm. Protocol
			Commentary			
1	<u>FL-RO1716</u>	FL-RO7AA	2. Acceptance of 1 an samples of street gr3. DIP switch to enable4. Synchronization by	nd 5 RON has bee rade bills. le / disable old 10 translucent optic	Romania 2008 has been introduced. In improved based on the latest RON has been introduced. Is signals has been implemented ansparent plastic RON bills.	CCNET
2	FL-RO1715	FL-RO7AA	the malfunction of M 2. Stacker cycle has b 3. Rejecting code "Co "Insertion error"(0x6	FL's centering me been added in cas nv. error"(0x64) h 50) for wrong insel cur only if both In	ee of rejecting from Stacking state. as been replaced with tions. out and Aligning sensors covered.	CCNET
3	FL-R01714	FL-RO7AA		-	Romania ts has been corrected in order due to "Denomination inhibit"	CCNET
4	FL-RO1713	FL-RO7AA	J1-4.13.hex 1. Processing of new 2. Processing of all ol		Romania in 2006 has been introduced. een disabled.	CCNET
5	FL-RO1612	FL-RO6AA		03/11/05 FL 5, 10, 50, 100 & 5	Romania 500 RON issued in 2005	CCNET
6	FL-R01411	FL-RO4AA	J1-4.11 Acceptance of 500000	08/11/04 FL 0 ROL bills has be	Romania een improved	CCNET
7	FL-RO1410	FL-RO4AA	J1-4.10 First release	03/09/04 FL	Romania	CCNET