Revision History

No	Item No.	File Name	Release Date Device	Country	Comm. Protocol	Commentary
1	FL-BY5610	FL-BY6AAG1-4.10	09/26/05 FL	BY	FL_BDG2	First release
2	FL-BY5611	FL-BY6AAG1-4.11	08/24/07 FL	BY	FL_BDG2	1.STACKER JAM flag is set to indicate BILL DROP condition in case if bill is
						lost during rejecting from STACKING state due to cheating or jam.
						2. FL does not detect bill removing from the drop cassette if the second
						bill is inserted.
3	FL-BY5712	FL-BY7AAG1-4.12.hex	08/24/07 FL	BY	FL_BDG2	Processing of new 100000 BYR issued in 2005 has been introduced.