

April 18, 2022

Revision History

ltem No.		Release Date	Device	Country	Comm. Protoco
Commentary		(mm/dd/yy)			
<u>BB-BHSA1682</u>		04/18/22	BB300	Bahrain + Saudi Arabia	CCNET
2. F 3. A 4. F Limit	Processing of old Acceptance rate mplemented aut power interruptic ations:	bill types 1, 5, 10, 50 for 5 SAR (2016) and tomatic restoring of t	and 100 SAR, issued 10 SAR (2007,2009)	2020, Commemorative) has been i in 1983-1984, has been disabled. nas been improved. capacity limit after restart ("Reset	
	Maintenance mode (cleaning card) is not supported.				
3.	Power recovery is limited because of transparent windows on the banknotes.				
	Bill retraction fur retraction (state	•	"Empty Dispenser" c	ommand must follow immediately	[,] after bill
BB-BHSA168	1	11/26/18	BB300	Bahrain + Saudi Arabia	CCNET
1.	Processing of ne	w 5 BHD (2018) has b	een introduced.		
1.	-	rcodes is disabled. ode (cleaning card) is	not supported.		
BB-BHSA168	<u>0</u>	08/23/18	BB300	Bahrain + Saudi Arabia	CCNET
First	release.				
0.5, 1		e of: ahraini Dinar (BHD); 200 and 500 Saudi Riy	val (SAR).		
	ations: Processing of Ba	rcodes is disabled			

- 1. Processing of Barcodes is disabled.
- 2. Maintenance mode (cleaning card) is not supported.

T. +1.905.851.9775 info@paycomplete.com www.paycomplete.com