

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-EU1111</u>	01/11/19	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Processing of new 100 EUR (2019) and 200 EUR (2019) has been introduced. 2. Counterfeits protection has been improved for 20 EUR. 				
<u>BB-EU1110</u>	04/09/18	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Additional timeout options for Dispenser Retraction are included (available with Chassis BB-BCA14946 only). 				
<u>BB-EU1109</u>	03/06/18	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Fixed regression which prevented Dispensing Command to be process properly after Power Cut or Failure. 2. Implemented workaround for potential recoverable bezel indication problem in Idling state. 				
<u>BB-EU1108</u>	06/07/17	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Detection and rejection of counterfeits 50 EUR (2002) has been improved based on samples from the field. 2. Support of 50 EUR (2017) banknotes with "R"-code, printed by BUNDESDRUCKEREI, has been added. 3. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser. 4. Implemented support for new BCU (Box Control Unit) with increased stacking force. 				
<u>BB-EU1107</u>	11/28/16	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Processing of new 50 EUR (2017) has been introduced. 2. Detection and rejection of paper infused banknotes has been implemented. 3. "EMPTY DISPENSER" command has been enabled in 0xCA failure state. 				
<u>BB-EU1106</u>	08/14/15	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Processing of new 20 EUR (2015) has been introduced. 2. Rejection of folded new 20 Euro has been improved to prevent cross-validation. 3. Detection and rejection of EUR counterfeits has been improved. 4. Overall acceptance rate has been improved. 5. Fixed Power recovery issues during stacking. 6. Fixed missing message about unloaded bills before BOX FULL message. 7. Corrected processing of Statistics counters for bills, packed into cassette after "Power cut during stacking". 8. Eliminated occasional false "BOX FULL" reports. 9. Improved stacking procedure for bills packed into Drop Box. 10. Eliminated false Power recovery report during initialization after BOX FULL message. 				
<u>BB-EU1105</u>	01/26/15	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Rejection of folded new 10 Euro has been improved to prevent cross-validation. 2. Overall acceptance has been improved in High Acceptance and High Security modes. 				

January 11, 2019

3. Detection and rejection of counterfeits has been improved.
4. "CashCode" was changed to "Suzo-Happ Group" everywhere.
5. Bill length transfer into chassis was implemented.
6. DISPENSED message added in case of Dispenser failure during Dispensing operation.
7. CCNET_READ_MODULES_ID support became enabled for Idling mode.
8. Credit message added when reset on accepting.
9. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.
10. Optical length filter was implemented.

<u>BB-EU1104</u>	09/08/14	BB300XE	Europe	CCNET
Introduction of new 10 EURO.				
<u>BB-EU1101</u>	03/13/13	BB300XE	Europe	CCNET
<ol style="list-style-type: none"> 1. Processing of new 5 EUR to be issued in 2013 has been introduced. 2. Performance improvement to 5, 20 and 50 EUR. 				
<u>BB-EU1100</u>	10/30/12	BB300XE	Europe	CCNET
First release for BB300XE.				