

September 8, 2022

## **Revision History**

Item No. Co	mmentary	Release Date (mm/dd/yy)	Device	Country	Comm. Protocol	
BB-EUGBNI1188		09/08/22	BB300	Europe + Great Britain + Northern Ireland	CCNET	
1.	-			for all bill types, issued before polymer series 24	018 - 2020:	
		gland: 20 GBP (2007	-			
		eland: 20 GBP ('1999				
	<ul> <li>Northern Bank: 20 GBP ('2005), Northern Bank / Danske Bank : 20 GBP ('2012).</li> <li>Ulster Bank: 20 GBP ('1996,'99,'02,'04,'06,'07,'08).</li> </ul>					
2.				, 08). cassette capacity limit after restart ("Reset" cor	mmand	
Ζ.	power interrup	-	of the recycling	casselle capacity inflit alter restart ( Reset cor	iiiiaiiu,	
3.	• •		ntial recoverab	le bezel indication problem in Idling state.		
4.	•			o "SDS-EUR3GBN3-R8".		
			·			
Limi 1.	tations:	is limited because	oftransparent	windows on the banknotes		
1. 2.	Power recovery is limited because of transparent windows on the banknotes. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill					
2.	retraction (stat				Sill	
BB-EUGBN	<u>  1187</u>	09/11/20	BB300	Europe + Great Britain + Northern Ireland	CCNET	
1.	-	hree new polymer b has been introduced.		BBP (issued in 2020 by Ulster Bank, Bank of Ireland	nd and	
2.	Improved the a bills, received f	•	5 and 10 GBP (N	Northern Ireland) based on the latest samples of	street grad	
3.	Overall accepta	ance rate has been ir	mproved.			
4.	-			1994,'96,'98) has been disabled.		
5.	-	eature has been imp				
6.	Eliminated fals	e bills rejection acco	mpanied by "C	HEATED" message.		
Limi	tations:					
1.	Power recovery	y is limited because	of transparent	windows on the banknotes.		
2.		•	d. "Empty Disp	enser" command must follow immediately after	bill	
	retraction (stat	e "CA").				
BB-EUGBN	11186	10/21/19	BB300	Europe + Great Britain + Northern Ireland	CCNET	
1.	Processing of n	ew polymer 20 GBP	to be issued in	2020 by Bank of England has been introduced.		
2.	-			eland) has been disabled:		
	-		-	d by Bank of Ireland,		
	- 5 GBP (199	3-2007), 10 GBP (19	99-2007) issue	d by Ulster Bank,		

- 5 GBP (1999-2000), 10 GBP (2005-2013) issued by Northern/Danske Banks,
- 10 GBP (1984-2012) issued by First Trust Bank.

SUZOHAPP Canada ULC 9225 Leslie St, Units 6-7, Richmond Hill, ON L4B 3H6, Canada T. +1.905.851.9775 info@paycomplete.com www.paycomplete.com

Pay Complete

September 8, 2022

3. "Anti-fishing" feature has been improved for polymer banknotes.

Limitations:

- 1. Power recovery is limited because of transparent windows on the banknotes.
- 2. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

BB-EUGBNI1185	03/20/19	BB300	Europe + Great Britain + Northern Ireland	CCNET
- 5, 10 GBF - 5, 10 GBF - 10 GBP (2	f new polymer bankno ? (2019, Bank of Irelar ? (2019, Ulster Bank), 2019, Danske Bank). f old 5, 10 & 20 EUR, is	nd),		
	n functionality is limite		windows on the banknotes. enser" command must follow immediately after	bill
BB-EUGBNI1184	03/09/18	BB300	Europe + Great Britain + Northern Ireland	CCNET
<ol> <li>Implemented</li> <li>Fixed CCNET</li> </ol>	d workaround for pote command applicabilit	ential recoverab y after bills retr	gland) has been disabled. ble bezel indication problem in Idling state. raction. ne unit when the banknotes are inside of dispens	ser.
	n functionality is limite	•	windows on the banknotes. enser" command must follow immediately after	bill
BB-EUGBNI1183	05/23/17	BB300	Europe + Great Britain + Northern Ireland	CCNET
<ol> <li>Processing of</li> <li>Acceptance r of scans and</li> <li>Detection and</li> </ol>	5 GBP (2002, Bank of ate for polymer 5 GBF street grade bills rece d rejection of paper ir	England) has b 2 (2016, Bank of ived from custo ifused banknot	f England) has been improved based on the lates	t samples
6. "EMPTY DISP	otance rate has been i ENSER" command is e	•	failure state.	
6. "EMPTY DISP Limitations:	ENSER" command is e	enabled in 0xCA	failure state. windows on the banknotes.	

- 1. Processing of new polymer 5 GBP (2016, Bank of England) has been introduced.
- 2. Overall acceptance rate has been improved.
- 3. Fixed an error in sensor synchronization that might lead to reduced acceptance rate.

SUZOHAPP Canada ULC 9225 Leslie St, Units 6-7, Richmond Hill, ON L4B 3H6, Canada

T. +1.905.851.9775 info@paycomplete.com www.paycomplete.com

## Pay Complete

September 8, 2022

## **BB-EUGBNI1181**12/15/15BB300Europe + Great Britain + Northern IrelandCCNET

BB300

1. Processing of new 20 EUR (2015) has been introduced.

02/20/15

- 2. Overall acceptance rate has been improved.
- 3. Reduced probability of false "CHEATED" reports.
- 4. Fixed Power recovery issues during stacking.
- 5. Fixed missing message about unloaded bills before BOX FULL message.

## Europe + Great Britain + Northern Ireland CCNET

This is a first release for BB300.

Supported acceptance of:

5, 10, 20 Euro (EUR)

**BB-EUGBNI1180** 

- 5, 10, 20 English Pound Sterling (GBP)
- 5, 10, 20 Northern Irish Pound Sterling (GBP).

SUZOHAPP Canada ULC 9225 Leslie St, Units 6-7, Richmond Hill, ON L4B 3H6, Canada T. +1.905.851.9775 info@paycomplete.com www.paycomplete.com