

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-IN1210</u>	12/24/19	BB200XE	India	CCNET
<ol style="list-style-type: none"> 1. Processing of new 20 INR (2019) has been introduced. 2. Acceptance rate for 10 INR (2005-2011, 2018), 20 INR (2005-2011), 50 INR (2017) and 100 INR (2018) has been improved based on the latest samples of street grade banknotes. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is disabled. 				
<u>BB-IN1209</u>	12/06/18	BB200XE	India	CCNET
<ol style="list-style-type: none"> 1. Processing of new 100 INR (2018) has been introduced based on scans received from customer. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is disabled. 				
<u>BB-IN1208</u>	05/11/18	BB200XE	India	CCNET
<ol style="list-style-type: none"> 1. Processing of new 10 INR (2018) has been introduced based on scans received from customer. 2. Acceptance rate for 20 INR (series 2011), 50 INR (series 2011) and 500 INR (series 2016) improved based on scans received from customer. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is disabled. 				
<u>BB-IN1207</u>	02/01/18	BB200XE	India	CCNET
<ol style="list-style-type: none"> 1. Acceptance rate for 50 INR (2017) and 200 INR (2017) has been improved based on the latest samples of street grade bills. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is disabled. 				
<u>BB-IN1206</u>	12/12/17	BB200XE	India	CCNET
<ol style="list-style-type: none"> 1. Processing of two new bill types 50 INR (2017) and 200 INR (2017) has been introduced based on scans received from customer. 2. Bill table has been modified to include 200 INR: "Bill type 5" is set to "200 INR", "Bill type 6" is set to "500 INR" (refer to User's Guide for details). 3. DIP Switches settings have been changed to include new denomination 200 INR: DIP Switch 1.6 is set to "200 INR", DIP Switch 1.7 is set to "500 INR" (refer to User's Guide for details). 4. Statistics counters have been modified. 5. Fixed CCNET command applicability after bills retraction. That prevents invalid/unexpected operations of the unit when the banknotes are inside of dispenser. 6. Implemented workaround for potential recoverable bezel indication problem in idling state. <p>Limitations:</p> <ol style="list-style-type: none"> 1. Diagnostics is disabled. 				

December 24, 2019

BB-IN1205	06/21/17	BB200XE	India	CCNET
------------------	----------	---------	-------	-------

1. Processing of new 500 INR (2016) and 2000 INR (2016) has been introduced.
2. Bill table modified to include 2000 INR (2016). Bill type "7" has been set to "2000 INR".
3. DIP Switch 1.8 is set to "2000 INR".
4. Processing of 100 INR, issued before 2005, has been disabled.
5. Processing of 500 INR, issued before 2016, has been disabled.
6. Segregation of banknotes 5, 10, 20 and 50 INR, issued before 2005 year, has been improved.
7. Processing of detection and rejection of mutilated banknotes in High Security mode has been improved.
8. Overall acceptance rate has been improved.
9. Implemented support for new BCU (Box Control Unit) with increased stacking force.
10. Diagnostic feature is enabled.

BB-IN1204	06/22/16	BB200XE	India	CCNET
------------------	----------	---------	-------	-------

Project is based on software BB-IN1303:

1. Reduced stacking force to prevent breakage of the gears with old BCU (Box Control Unit).
2. Rejection of "mutilated" banknotes of 10 INR (2005, 2006 Issue; 2011 Issue), 100 INR (1996-2002 Issue) and 100 INR (2005, 2006 Issue; 2011 Issue) has been improved based on scans received from customer.

Limitations:

1. Drop Box capacity is reduced to 750-850 notes with old BCU (Box Control Unit).
2. Diagnostics is not supported.

BB-IN1203	05/19/16	BB200XE	India	CCNET
------------------	----------	---------	-------	-------

1. First release for BB200XE to enable upgrade path based on BB-IN1302.
2. 5, 10, 20, 50, 100, 500 INR acceptance supported.
3. Rejection of "mutilated" banknotes of 10 INR (2005, 2006 Issue; 2011 Issue), 100 INR (1996-2002 Issue) and 100 INR (2005, 2006 Issue; 2011 Issue) has been improved based on scans received from customer.

Limitations:

1. Diagnostics is not supported.