

May 19, 2016

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
Commentary				
<u>BB-IN1303</u>	05/19/16	BB100XE	India	CCNET
<ol style="list-style-type: none">1. Reduced stacking force to prevent breakage of the gears.2. Rejection of "mutilated" banknotes of 10 INR (2005, 2006 Issue; 2011 Issue), 100 INR (1996-2002 Issue) and 100 INR (2005, 2006 Issue; 2011 Issue) has been improved based on scans received from customer. <p>Limitations:</p> <ol style="list-style-type: none">1. Drop Box capacity is reduced to 750-850 notes.2. Diagnostics is not supported.				
<u>BB-IN1302</u>	12/09/14	BB100XE	India	CCNET
<ol style="list-style-type: none">1. Rejection of mutilated banknotes (specially taped, torn and glued notes) in High Security mode has been improved for all denominations.2. Overall acceptance rate has been improved.				
<u>BB-IN1301</u>	12/09/14	BB100XE	India	CCNET
<ol style="list-style-type: none">1. Segregation of bills, issued before 2005 year, has been implemented.2. Overall acceptance rate has been improved.3. Infinite initialization cycle is fixed. Unit can exit this multifunction state upon reception "RESET" command.				
<u>BB-IN1300</u>	03/19/14	BB100XE	India	CCNET
<p>First release for BB100XE.</p> <p>5, 10, 20, 50, 100, 500 INR acceptance supported.</p>				