

Revision History

 Item No.
 Release Date Date (mm/dd/yy)
 Device Double Device Device Device Date Protocol Device Date (mm/dd/yy)
 Country Device Dev

- Bank of England: 20 GBP (2007).

The Royal Bank of Scotland: 20 GBP (1991 ['91-'98,'99-'12,'16]).
Bank of Scotland: 20 GBP (1995 ['95-'98,'99-'01,'03]; 2007).

- Clydesdale Bank: 20 GBP (1994 ['96]; 1997 ['99,'02,'03,'04]; 1997 (Commemorative issue);

Processing of old paper 20 GBP has been disabled for all bill types, issued before polymer series 2018 - 2019:

1999 (Commemorative issue); 2005 (Commemorative issue); 2006, 2009).

2. Supported Denomination Set has been updated to "SDS-GBS3-R10".

Limitations:

- Barcodes processing is disabled.
- 2. Maintenance mode (cleaning card) support is disabled.
- 3. Power recovery is limited because of transparent windows on the banknotes.
- 4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

XB-GBS1103 07/26/21 BB300XT England + Scotland CCNET

- Acceptance rate for polymer 5 GBP (The Royal Bank of Scotland), 20 GBP (Bank of England) and 20 GBP (Bank of Scotland) has been improved based on the latest samples of street grade banknotes received from customer.
- 2. Overall acceptance rate for polymer bill types has been improved.
- 3. Implemented automatic restoring of the recycling cassette capacity limit after restart (reset command, power interruption, etc.)

Limitations:

- 1. Barcodes processing is disabled.
- 2. Maintenance mode (cleaning card) support is disabled.
- 3. Power recovery is limited because of transparent windows on the banknotes.
- 4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

XB-GBS1102 10/06/20 BB300XT England + Scotland CCNET

- 1. Processing of polymer 5 GBP and polymer 20 GBP (Bank of Scotland, The Royal Bank of Scotland, Clydesdale Bank) has been improved based on the received samples of street grade banknotes.
- 2. Eliminated bills false rejection accompanied by "CHEATED" message for polymer 10 GBP (Scottish bill types).

Limitations:

Barcodes processing is disabled.



- 2. Maintenance mode (cleaning card) support is disabled.
- 3. Power recovery is limited because of transparent windows on the banknotes.
- Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

XB-GBS1101 05/19/20 BB300XT England + Scotland CCNET

- Processing of new bill types 20 GBP (2019, Bank of England), 20 GBP (2019, Bank of Scotland),
 20 GBP (2019, The Royal Bank of Scotland) and 20 GBP (2019, Clydesdale Bank) has been introduced.
- 2. Artificial Currency Code "GBS" is used in Bill Table for Scottish banknotes recognition.
- 3. Bill table has been modified to separate English and Scottish bill types (refer to User's Guide for details):
 - Bill Types "0", "1", "2" are used for 5, 10, 20 GBP (English Pound Sterling) accordingly.
 - Bill Types "3", "4", "5" are used for 5, 10, 20 GBS (Scottish Pound Sterling) accordingly.
- 4. DIP Switches settings have been rearranged to separate English and Scottish bill types (refer to User's Guide for details):
 - DIP Sw. 1.1, 1.2, 1.3 are set to enable/disable 5, 10, 20 GBP (English Pound Sterling) accordingly.
 - DIP Sw. 1.4, 1.5, 1.6 (previously "Reserved") are set to enable/disable 5, 10, 20 GBS (Scottish Pound Sterling) accordingly.

Limitations:

- 1. Barcodes processing is disabled.
- 2. Maintenance mode (cleaning card) support is disabled.
- 3. Power recovery is limited because of transparent windows on the banknotes.
- 4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").

XB-GBS1100 09/14/18 BB300XT England + Scotland CCNET

First release.

Supported acceptance of:

- 5, 10, 20 English Pound Sterling (GBP),
- 5, 10, 20 Scottish Pound Sterling (GBP)

Limitations:

- 1. Barcodes processing is disabled.
- 2. Maintenance mode (cleaning card) support is disabled.
- 3. Power recovery is limited because of transparent windows on the banknotes.
- 4. Bill retraction functionality is limited. "Empty Dispenser" command must follow immediately after bill retraction (state "CA").