

Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<u>FL-AR2019</u>	03/20/20	(M)FL	Argentina	FL_BDP
Commentary 1. Processing of 100 ARS (2018) has been added. 2. Overall acceptance rate has been improved.				
<u>FL-AR2018</u>	12/10/18	(M)FL	Argentina	FL_BDP
1. Processing of new 50 ARS (2018) has been introduced. 2. Processing of 20 ARS (2017) and 1000 ARS (2017) has been added. 3. Processing of 2 ARS (all year's issue) has been disabled. 4. Overall acceptance rate has been improved. 5. Bill table has been modified to include the new denomination 1000 ARS and exclude 2 ARS (refer to User's Guide for details): - "62H" is set to "not used" (previously was assigned to "2 ARS"), - "69H" has been set to "1000 ARS" ("69H" was not previously used). 6. DIP Switches settings have been modified (refer to User's Guide for details): - DIP Switch 1.2 is set to "1000 ARS" (previously assigned to "2 ARS").				
<u>FL-AR2017</u>	10/11/17	(M)FL	Argentina	FL_BDP
1. Processing of 5 and 50 ARS (series 2015), and 10, 100, 200 and 500 ARS (series 2016) has been added. 2. Bill table has been changed to include two new denominations 200 and 500 ARS: "61H" has been set to "500 ARS", "68H" has been set to "200 ARS". 3. DIP Switches settings have been changed to include two new denominations 200 and 500 ARS: DIP Switch 1.1 is set to "500 ARS", DIP Switch 1.8 is set to "200 ARS". 4. Statistics counters have been modified to include all added bill types. 5. Overall acceptance rate has been improved. 6. Greeting message changed to "SUZOHAPP".				
<u>FL-AR2016</u>	12/16/13	(M)FL	Argentina	FL_BDP
Acceptance rate of new 100 ARS issued in 2012 has been improved based on the latest samples of street grade bills.				
<u>FL-AR2015</u>	02/19/13	(M)FL	Argentina	FL_BDP
1. Processing of new 100 ARS issued in 2012 has been introduced. 2. Performance improvement to 100 ARS.				
<u>FL-AR2613</u>	10/15/08	(M)FL	Argentina	FL_BDP
1. Counterfeit protection has been improved based on the latest samples of 20 and 100 ARS counterfeits. 2. Acceptance of 100 ARS has been improved according to the latest samples of street grade bills. 3. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.				

March 20, 2020

4. Pause state will occur only if both Input and Aligning sensors covered.
5. 10 sec timeouts implemented in Pause state.

<u>FL-AR2612</u>	05/01/08	(M)FL	Argentina	FL_BDP
-------------------------	----------	-------	-----------	--------

1. Counterfeit protection has been improved based on the latest samples of 20 ARS counterfeits.
2. Acceptance of 100 ARS has been improved according to the latest samples of street grade bills.

<u>FL-AR2611</u>	05/31/05	(M)FL	Argentina	FL_BDP
-------------------------	----------	-------	-----------	--------

Acceptance rate has been improved; counterfeit protection has been enhanced.

<u>FL-AR2601</u>	03/08/04	(M)FL	Argentina	FL_BDP
-------------------------	----------	-------	-----------	--------

First release.