Revision History

No	Item No.	File Name	Release	Device	Country	Comm. Protocol
NO	item No.	Commen		Device	Country	Comm. Protocol
			,			
1	FL-MY2619	FL-MY3AAD0-4.19.h	nex 31/03/09	FL	Malaysia	FL_BDP
		1. Acceptance of new 50 MYR has been improved according to the latest samples				
		of street grade bills.				
		2. Checking of drop box presence has been added for the case when returned				
		bill is held in the entry slot.				
2	FL-MY2618	FL-MY3AAD0-4.18.h	nex 26/03/08	FL	Malaysia	FL_BDP
		1. Processing of new 50 MYR issued in 2007 has been introduced.				
		2. 1, 2 and 5 MYR have been excluded from bill processing.3. Stacker cycle has been added in case of rejecting from stacking state.				
		4. "Program signature" command has been introduced.				
		5. Rejecting code "Feed error"(0x75) has been replaced with				
		"Insertion error"(0x71).				
3	FL-MY2615	FL-MY6AAD0-4.15.h	nex 29/06/06	FL	Malaysia	FL_BDP
		Overall acceptance rate has been improved according to the latest samples				
		of street grade bills.				
4	FL-MY2613	FL-MY6AAD0-4.13	26/07/05	FL	Malaysia	FL_BDP
		1. Acceptance of 10, 50 & 100 MYR bills has been improved according to				
		the latest samples of street money.				
		2. Processing of new 5 MYR issued in 2004 has been added.3. Processing of 2 MYR bills has been added.				
5	FL-MY2512	FL-MY5AAD0-4.12	13/08/04	FL	Malaysia	FL BDP
	Acceptance of 10 & 50 MYR has been improved					
6	FL-MY2511	FL-MY5AAD0-4.11	19/07/04		Malaysia	FL_BDP
		ID code (Boot version) has been changed to B319				
7	FL-MY2501	FL-MY5AAD0-4.10	24/11/03	FL	Malaysia	FL BDP
		First rele	ease		•	_