

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b><u>FL-TH1124</u></b>	05/10/19	(M)FL	Thailand	CCNET
Commentary 1. Processing of new 500 and 1000 THB, issued in 2018, has been introduced. 2. Overall acceptance rate has been improved.				
<b><u>FL-TH1123</u></b>	07/03/18	(M)FL	Thailand	CCNET
1. Processing of new 20, 50 and 100 THB, issued in 2018, has been introduced. 2. Overall acceptance rate has been improved.				
<b><u>FL-TH1122</u></b>	02/02/18	(M)FL	Thailand	CCNET
1. New commemorative note family of 20 THB (2017), 50 THB (2017), 100 THB (2017), 500 THB (2017) and 1000 THB (2017) has been introduced. 2. Overall acceptance rate has been improved.				
<b><u>FL-TH1121</u></b>	10/29/15	(M)FL	Thailand	CCNET
1. Processing of 1000 THB (2015) has been introduced. 2. Overall acceptance rate has been improved. 3. Processing of Barcodes has been improved. 4. Fixed wrong credit messages during Power Recovery.				
<b><u>FL-TH1120</u></b>	04/16/15	(M)FL	Thailand	CCNET
1. Processing of 100 THB (2014) has been introduced. 2. Acceptance rate for 100 THB (2005) and 1000 THB (2005) has been improved.				
<b><u>FL-TH1119</u></b>	07/15/14	(M)FL	Thailand	CCNET
Processing of new 500 THB (2014) has been introduced.				
<b><u>FL-TH1118</u></b>	05/30/13	(M)FL	Thailand	CCNET
Processing of new 20 THB issued in 2013 has been introduced.				
<b><u>FL-TH1117</u></b>	03/04/13	(M)FL	Thailand	CCNET
Improved calculation of maximum allowed bill length has been brought in.				
<b><u>FL-TH1116</u></b>	02/20/13	(M)FL	Thailand	CCNET
Processing of new 50 THB issued in 2012 has been introduced.				
<b><u>FL-TH1515T</u></b>	10/30/12	(M)FL	Thailand	CCNET

---

 Improve acceptance of 20 THB.
 

---

<b><u>FL-TH1514</u></b>	02/06/09	(M)FL	Thailand	CCNET
-------------------------	----------	-------	----------	-------

1. Processing of 20 and 50 THB has been introduced.
  2. Stacker cycle added in case of rejecting from stacking state.
  3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.
  4. Pause state will occur if both Input and Aligning sensors covered.
  5. 10 sec. timeout implemented in Pause state.
  6. Checking of drop box presence has been added for the case when returned bill is held in the entry slot.
- 

<b><u>FL-TH1313</u></b>	07/24/07	(M)FL	Thailand	CCNET
-------------------------	----------	-------	----------	-------

Acceptance of 100 & 1000 THB has been improved according to the latest samples of street grade bills.

---

<b><u>FL-TH1312</u></b>	09/15/06	(M)FL	Thailand	CCNET
-------------------------	----------	-------	----------	-------

Processing of new 100 THB issued in 2006 has been introduced.

---

<b><u>FL-TH1311</u></b>	03/13/06	(M)FL	Thailand	CCNET
-------------------------	----------	-------	----------	-------

1. Processing of new 100 & 1000 THB issued in 2005 has been added.
  2. Part number and boot version information has been added to statistics.
  3. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".
- 

<b><u>FL-TH1310</u></b>	11/08/04	(M)FL	Thailand	CCNET
-------------------------	----------	-------	----------	-------

First release.

---