

June 14, 2016

## **Revision History**

Item No.		Release Date	Device	Country	Comm. Protocol
Соі	mmentary				
FL-TH2023		06/14/16	(M)FL	Thailand	FL_BDP
1. 2. 3. 4.	Processing of 20 THB (2003, 2013) and 50 THB (2004, 2005, and 2012) has been enabled.  Bill table modified to include 20 THB and 50 THB (Escrow Code "62H" has been set to "20 THB" and Escrow Code "63H" has been set to "50 THB").  DIP Switches settings have been rearranged (refer to User's Guide for details).  Acceptance rate has been improved for 100 THB (1994, 2014) and 500 THB (2014).				
FL-TH2021		11/05/15	(M)FL	Thailand	FL_BDP
1. 2.	Processing of new 1000 THB (2015) has been introduced.  Overall acceptance rate has been improved.				
FL-TH2019		04/23/15	(M)FL	Thailand	FL_BDP
1. 2.	Processing of 100 THB (2014) has been introduced. Acceptance rate for 100 THB (2005) and 1000 THB (2005) has been improved.				
FL-TH2017		07/19/14	(M)FL	Thailand	FL_BDP
Pro	Processing of new 500 THB (2014) has been introduced.				
FL-TH2315		07/09/07	(M)FL	Thailand	FL_BDP
Pro	Processing of new 100 THB issued in 2005 has been introduced.				
FL-TH2313		03/21/06	(M)FL	Thailand	FL_BDP
1. 2. 3. 4.	Acceptance of new 100 THB has been improved according to the latest samples of street money. Processing of new 1000 THB issued in 2005 has been added.  Part number and boot version information has been added to statistics.  Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".				
FL-TH2311		07/28/05	(M)FL	Thailand	FL_BDP
Ove	Overall acceptance has been improved according to the latest samples of street money.				
FL-TH2310		05/21/04	(M)FL	Thailand	FL_BDP
Firs	t release.				

SUZOHAPP • 1743 Linneman Road • Mount Prospect, IL 60056 • Phone: 847-593-6130 • Fax: 847-593-6137