

June 16, 2016

## **Revision History**

Item No.		Release Date	Device	Country	Comm. Protocol
Соі	nmentary				
FL-TH5518		06/16/16	(M)FL	Thailand	FL_BDG2
1. 2. 3. 4.	Processing of 20 THB (2003, 2013) and 50 THB (2004, 2005, and 2012) has been enabled.  Bill table modified to include 20 THB and 50 THB (in Bill Table "Type 2" has been set to "20 THB" and "Type 3" has been set to "50 THB").  DIP Switches settings have been rearranged (refer to User's Guide for details).  Acceptance rate has been improved for 100 THB (1994, 2014) and 500 THB (2014).				
FL-TH5517		11/12/15	(M)FL	Thailand	FL_BDG2
1. 2. 3.	Processing of 1000 THB ( Overall acceptance rate I Fixed missing device stat	nas been improved			
FL-TH5516		05/01/15	(M)FL	Thailand	FL_BDG2
1. 2.	Processing of 100 THB (2014) has been introduced. Acceptance rate for 100 THB (2005) and 1000 THB (2005) has been improved.				
FL-TH5515		08/05/14	(M)FL	Thailand	FL_BDG2
Pro	cessing of new 500 THB (2014) has been introduced.				
FL-TH5314		07/30/07	(M)FL	Thailand	FL_BDG2
1. 2.	Processing of new 100 THB issued in 2005 has been introduced. Acceptance of 1000 THB has been improved according to the latest samples of street grade bills.				
FL-TH5313		07/04/06	(M)FL	Thailand	FL-BDG2
1. 2. 3.	Processing of new 100 & 1000 THB issued in 2005 has been added. Part number and boot version information have been added to statistics. Statistics counter "Jam at Entrance" has been changed to "Returned bill by Cross Sensor".				
FL-TH5312		09/07/05	(M)FL	Thailand	FL-BDG2
	STACKER JAM flag is set to indicate BILL DROP condition in case if the bill lost during rejecting from STACKING state due to cheating or jam. FL does not detect bill removing from the drop cassette if the second bill is inserted.				
FL-TH5311		07/25/05	(M)FL	Thailand	FL-BDG2
	erall acceptance has been		•		-



June 16, 2016

<u>FL-TH5310</u> 05/21/04 (M)FL Thailand FL-BDG2

First release.