

## Revision History

Item No.	Release Date	Device	Country	Comm. Protocol
<b>FL-ZN5519</b>	06/25/18	(M)FL	South Africa + Namibia	FL-BDG2
Commentary 1. Processing of new banknotes 10, 20, 50, 100 and 200 ZAR, issued in 2018 to commemorate the 100th anniversary of the birth of Nelson Mandela, has been introduced. 2. Support of ZAR banknotes with Omron feature has been added (series 2012, banknotes printed in 2013-2014). 3. Support of 10 NAD (2015) and 20 NAD (2015) has been added. 4. Processing of 10, 20, 50 and 100 ZAR, issued before 2005, has been disabled. 5. Overall acceptance rate has been improved. 6. Greeting message has been changed to "SUZOHAPP".				
<b>FL-ZN5517</b>	05/16/14	(M)FL	South Africa + Namibia	FL-BDG2
1. Overall acceptance rate has been improved.				
<b>FL-ZN5516</b>	06/30/13	(M)FL	South Africa + Namibia	FL-BDG2
1. Processing of new 10, 20, 50, 100 and 200 ZAR issued in 2012 has been introduced. 2. DIP switch to enable / disable old ZAR and NAD acceptance has been brought in. 3. Acceptance of new 10 and 20 NAD issued in 2012 has been improved based on the latest samples of street grade bills.				
<b>FL-ZN5515</b>	07/11/12	(M)FL	South Africa + Namibia	FL-BDG2
1. Processing of new 10 NAD, 20 NAD, 50 NAD, 100 NAD and 200 NAD issued in 2012 has been introduced.				
<b>FL-ZN5514</b>	08/17/10	(M)FL	South Africa + Namibia	FL-BDG2
1. Processing of old 200 ZAR has been disabled.				
<b>FL-ZN5513</b>	04/09/10	(M)FL	South Africa + Namibia	FL-BDG2
1. Acceptance of 10 NAD has been improved based on the latest samples of street grade bills.				
<b>FL-ZN5512</b>	10/05/09	(M)FL	South Africa + Namibia	FL-BDG2
1. Overall acceptance rate has been improved based on the latest samples of street grade bills. 2. DIP switch "High Acceptance / High Security" sets acceptance mode for stain notes.				
<b>FL-ZN5511</b>	06/04/08	(M)FL	South Africa + Namibia	FL-BDG2
1. Country selection by DIP switch has been excluded. This SW accepts both ZAR and NAD with the same credit for the same denomination. 2. One Way DIP switch has been disabled. 3. In case of fast feeding bill will be rejected only if both Input and Aligning sensors are covered. 4. FL detects cash box removal when the bill has been rejected or returned and is held at entry sensor.				

---

June 25, 2018

5. Accepting and rejecting states will not be reported in case of feeding error.
6. Request Bill Enables command is not masked with real denominations mask.
7. Barcode acceptance for 14 to 18-digits barcodes has been enabled.
8. Stored settings cleared in Service mode.

---

**FL-ZN5510**

09/20/07

(M)FL

South Africa + Namibia

FL-BDG2

First Release.