

Revision History

May 12, 2010

Page 1

No	Item No.	File Name	Release		Country	Comm. Protocol
			Date	Device		
1	<u>FL-GBS1322</u>	FL-GBS3AAJ1-4.22.hex	05/12/10	FL	England&Scotland	CCNET
		Processing of old 20 GBP (Bank of England) has been disabled.				
2	<u>FL-GBS1321</u>	FL-GBS3AAJ1-4.21.hex	12/10/09	FL	England&Scotland	CCNET
		Processing of new 5, 10 and 20 GBP issued by Clydesdale bank in 2009 has been introduced.				
3	<u>FL-GBS1320</u>	FL-GBS3AAJ1-4.20.hex	05/12/08	FL	England&Scotland	CCNET
		1. Acceptance of old 20 GBP (Bank of Scotland) has been improved according to the latest samples of street grade bills.				
		2. Stacker cycle added in case of rejecting from stacking state.				
		3. Rejecting code "Conv. error"(0x64) has been replaced with "Insertion error"(0x60) for wrong insertions.				
		4. Pause state will occur if both Input and Aligning sensors covered.				
		5. 10 sec timeout implemented in Pause state.				
4	<u>FL-GBS1319</u>	FL-GBS3AAJ1-4.19.hex	02/04/08	FL	England&Scotland	CCNET
		1. Processing of new 5, 10 & 20 GBP issued in 2007 by Bank of Scotland has been introduced as well as processing of 5 GBP (Royal bank) issued in 2004 and 20 GBP (Clydesdale bank) issued in 2005.				
		2. Overall acceptance has been improved according to the latest samples of street grade bills.				
5	<u>FL-GBS1318</u>	FL-GBS3AAJ1-4.18.hex	03/21/07	FL	England&Scotland	CCNET
		Processing of new 20 English pounds issued in 2007 has been introduced.				
6	<u>FL-GBS1317</u>	FL-GBS3AAJ1-4.17	01/05/06	FL	England&Scotland	CCNET
		Verification of the length of communication messages between FL and host controller has been implemented to prevent the wrong jump to download mode in Initialize state.				
7	<u>FL-GBS1316</u>	FL-GBS3AAJ1-4.16	11/02/05	FL	England&Scotland	CCNET
		1. Acceptance of new 5 England Pounds has been improved.				
		2. Old England pounds have been removed from bill processing.				
8	<u>FL-GBS1306</u>	FL-GBS3AAJ1-4.15	05/03/04	FL	England&Scotland	CCNET
		Support of old-fashioned bezel with running lights has been added				
9	<u>FL-GBS1305</u>	FL-GBS3AAJ1-4.14	04/13/04	FL	England&Scotland	CCNET
		Acceptance has been improved based on latest samples of street money; old 5 Eng. pounds have been removed				
10	<u>FL-GBS1304</u>	FL-GBS3AAJ1-4.13	01/20/04	FL	England&Scotland	CCNET
		Acceptance				
11	<u>FL-GBS1303</u>	FL-GBS3AAJ1-4.12	10/09/03	FL	England&Scotland	CCNET
		Added new 5 Pounds. Add Credit Recovery. Close bill pass in Escrow. Fix unknown rejecting code. New barcode processing.				