

Revision History

June 15, 2011

Page 1

No	Item No.	File Name	Release			Country	Comm. Protocol
			Date	Device			
1	<u>FL-MY5522</u>	FL-MY3AAG1-5.22.hex	06/15/11	FL	Malaysia	FL-BDG2	
		Commentary					
		1. Counterfeit protection has been improved according to the latest samples of 50 MYR suspect notes.					
		2. Overall acceptance has been improved based on the latest samples of street grade bills.					
3	<u>FL-MY5521</u>	FL-MY3AAG1-4.21.hex	01/26/10	FL	Malaysia	FL-BDG2	
		Counterfeit protection has been improved according to the latest samples of 50 MYR counterfeits.					
5	<u>FL-MY5520</u>	FL-MY3AAG1-4.20.hex	03/31/09	FL	Malaysia	FL-BDG2	
		Acceptance of new 50 MYR issued in 2007 has been improved based on the latest samples of street grade bills.					
6	<u>FL-MY5519</u>	FL-MY3AAG1-4.19.hex	05/21/08	FL	Malaysia	FL-BDG2	
		1. Processing of new 50 MYR issued in 2007 has been introduced.					
		2. 1, 2 & 5 MYR have been disabled.					
		3. Stacker cycle added in case of rejecting from stacking state.					
		4. Bill will be rejected in case of fast feeding only if both Input and Aligning sensors covered.					
		5. FL detects cash box removal when the bill has been rejected or returned and is held at entry sensor.					
7	<u>FL-MY5517</u>	FL-MY6AAG1-4.17.hex	07/06/06	FL	Malaysia	FL-BDG2	
		Overall acceptance rate has been improved according to the latest samples of street grade bills.					
8	<u>FL-MY5515</u>	FL-MY6AAG1-4.15	10/03/05	FL	Malaysia	FL-BDG2	
		1. STACKER JAM flag is set to indicate BILL DROP condition in case if the bill lost during rejecting from STACKING state due to cheating or jam.					
		2. FL does not detect bill removing from the drop cassette if the second bill is inserted.					
		3. Acceptance of 2 MYR has been improved based on the latest samples of street money.					
9	<u>FL-MY5514</u>	FL-MY6AAG1-4.14	08/02/05	FL	Malaysia	FL-BDG2	
		1. Acceptance of 10, 50, 100 MYR has been improved.					
		2. Processing of 2 MYR bills has been added.					
10	<u>FL-MY5513</u>	FL-MY5AAG1-4.13	02/04/05	FL	Malaysia	FL-BDG2	
		Correction of bill tables has been implemented ; new dip switch for bill tables has been added.					
11	<u>FL-MY5512</u>	FL-MY5AAG1-4.12	01/24/05	FL	Malaysia	FL-BDG2	
		Dual bill tables have been implemented & new RG5.00 note has been added.					
12	<u>FL-MY5511</u>	FL-MY5AAG1-4.11	08/16/04	FL	Malaysia	FL-BDG2	
		Acceptance of 10 & 50 MYR has been improved					
13	<u>FL-MY5510</u>	FL-MY5AAG1-4.10	05/03/04	FL	Malaysia	FL-BDG2	
		First release					