

Revision History

| No | Item No. | File Name | Release Date | Device | Country | Comm. Protocol | Commentary |
|----|-------------------------|---------------------|--------------|--------|---------|----------------|--|
| 1 | <u>FL-UA5801</u> | FL-UA8AAG1-4.10 | 08/02/06 | FL | UKRAINE | FL-BDG2 | <i>20('04) & 50('04)UAH added; acceptance</i> |
| 3 | <u>FL-UA5811</u> | FL-UA8AAG1-5.11 | 08/02/06 | FL | UKRAINE | FL-BDG2 | <i>1. STACKER JAM flag is set to indicate BILL DROP condition in case if the bill lost during rejecting from STACKING state due to cheating or jam. 2. FL does not detect bill removing from the drop cassette if the second bill is inserted.</i> |
| 4 | <u>FL-UA5812</u> | FL-UA8AAG1-5.12.hex | 11/25/06 | FL | UKRAINE | FL-BDG2 | <i>Counterfeit protection has been enhanced according to the latest samples of 10 UAH counterfeits.</i> |
| 5 | <u>FL-UA5814</u> | FL-UA8AAG1-5.14.hex | 11/25/06 | FL | UKRAINE | FL-BDG2 | <i>1. Additional check of minimum stacker time has been implemented in order to eliminate cassette jams reported by Ritzio. 2. Processing of new 1, 10 & 100 UAH issued in 2006 has been introduced.</i> |